

Last updated: 21/11/2023 02:00:33

# FLUID SECTION REPAIR KIT F/MOD. 307

Product group: **427** Product number: **607832**

Fluid section repair kit (diaphragms/balls/seats) for mod. 307, polypropylene



## Product information

## Specification

General

Invent Hazard Material (IMO/EU) classification	NA
--	----

## Documents

[SDoC and MD for IHM](#)

## Related products

Is accessory to

**604918**  
DOUBLE DIAPHRAGM PUMP 307 POLY

Is frequently bought together with

**191874**  
20 UPMPLUG 1/4" MALE BSP.T

**607833**  
AIR VALVE KIT

**191684**  
30 USH SOCKET 3/8" HOSE

**552497**  
ELECTRODE HOLDER TWISTY 200AMP

**513051**  
ELECTRODE HOLDER TWISTY 400AMP

This page is printed from

<https://www.wilhelmsen.com/product-catalogue/products/pumps/accessories--spares/diaphragm-accessories--spares/fluid-section-repair-kit-fmod.-307>